

30, T35, R4E


CORNER RECORD

Document Number 06-0430

City of PALM SPRINGS

County of RIVERSIDE, California

Brief Legal Description LOT 87, MB 29/31-82



CORNER TYPE

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey \_\_\_\_\_

COORDINATES (Optional)

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ NAD27  NAD83   
NAD83 Epoch \_\_\_\_\_  
Elev. \_\_\_\_\_  
Vert. Datum: NGVD29  NAVD88   
Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

① FOUND 1" IP D.N. 0-1 W/ PLUG STAMPED RE 5876, NO RECORD, ACCEPTED AS CENTERLINE MONUMENT PER MB 29/31-82  
② FOUND 2x2 W/TAG FLUSH STAMPED LS 4152, ACCEPTED AS NE CORNER OF LOT 86  
③ FOUND 2x2 FLUSH ACCEPTED AS LOT CORNER PER MB 29/31-82 SET TAG LS 6500

A description of the physical condition of the monument as found and as set or reset:

④ SET 1" IP W/ PLASTIC PLUG STAMPED LS 6500, FLUSH

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on April 14, 2006

Signed [Signature] P.L.S. or R.C.E. No. 6500



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 4-25-06

and examined and filed 5-18-06

Signed [Signature] P.L.S. or R.C.E. No. 4993

Title COUNTY SURVEYOR



County Surveyor's Comment \_\_\_\_\_

THE FILING OF THIS CORNER RECORD DOES NOT RELIEVE THE SURVEYOR FROM ANY RESPONSIBILITY OF THE FILING OF A RECORD OF SURVEY

06-0294

30/3/4

● FOUND MONUMENTS AS NOTED

○ SET 1" I.P W/ PLASTIC PLUG STAMPED LS 6500, FLUSH

ALL BEARINGS & DISTANCES ARE MEAS & REC MB-29/81-82



N.T.S

